

Oil Field Environmental Incident Summary

Incident: 20160222120548 **Date/Time of Notice:** 02/22/2016 12:05

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: CAHILL-HELLING 13-20

Field Name: PRONGHORN

Well File #: 11371

Date Incident: 2/19/2016 **Time Incident:** 17:40

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 101

Sec: 20

Qtr: SW NW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 3000 Feet

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	20	Gallons	20	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/12/2016

Clean Up Concluded: 7/11/2016

Risk Evaluation:

None

Areal Extent:

approximately 100' x 150'

Potential Environmental Impacts:

Minimal, only a light mist of oil left site. Absorbent booms in place to capture any runoff. Soil samples taken of impacted area.

Action Taken or Planned:

Valve was closed and plugged. A vacuum truck was called to recover oil inside the dikes. Equipment will be cleaned weather permitting. Remediation of site to start immediately. Meeting with landowner scheduled for off site cleanup plan.

Wastes Disposal Location: Liquids at Nygaard SWD, and solids at Secure 13 mile corner.

Agencies Involved:**Updates**

Date: 2/22/2016 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Murex EHS coordinator emailed me details of the spill on 2/21/2016.

Murex is waiting to hear back from the landowner before they begin to remediate the location. The have placed booms to prevent the contamination from spreading.

More follow-up is necessary.

Date: 2/22/2016 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. More follow-up is necessary.

Date: 2/23/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/23/2016 at 15:24, on location. Impacted wheat stubble visible in field to southeast of wellpad. Snow has melted, leaving stained wheat stubble behind. More follow-up required.

Date: 2/24/2016 **Status:** Correspondence

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The company representative has a meeting with the landowner to develop a cleanup plan. They will provide us with details.

Date: 3/14/2016 **Status:** Correspondence

Author: Tintes Schiwal, Emily

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The company representative submitted photos of the testing coordinates and laboratory results. The laboratory results show all samples to be non detect for total petroleum hydrocarbons (TPH), gasoline range organics (GRO), and diesel range organics (DRO). Laboratory results and photos are in the corresponding folder.